



Product Change Notice (PCN)

Date: 10/30/15

PCN Number: 103015-01

To Our Customers:

We appreciate your use of our products. Our commitment in maintaining and improving processes is demonstrated by plans to enhance our product quality, reliability, and manufacturability. The purpose of this notice is to inform you of a product change.

Product(s) Affected:

| | | |
|------------------|-----------|------------------|
| CMC-5044TF-A | CPE-352 | CMT-1603-SMT-TR |
| CMC-5042PF-AC | CPE-200 | CMT-1261-SMT |
| CMC-5044PF-A | CPE-220 | CMI-1240-SMT |
| CMC-2742PBJ-A | CPE-253 | CPE-243 |
| CMC-2242PBL-A | CPE-270 | CPE-267 |
| CMR-2747PB-A | CPE-270H | CPE-244 |
| CMC-2742WBL-25L | CPE-350 | CPE-502 |
| CME-1538-100LB | CPE-351 | CPE-222H |
| CMC-2242PBL-A-C2 | CPE-353 | CPE-223 |
| CMC-2742WBL-C2 | CPE-353A | CPE-203 |
| CMC-5044TF-A-C3 | CPE-420 | CVS-1508 |
| CME2738WBJG34-C1 | CPE-400AC | CVS-1708 |
| CMC-5042PF-AC-C1 | CPE-422AC | CVS-2308 |
| CEP-2202A | CPE-460 | CVS-3108 |
| CEP-2202AS | CPE-750 | CDM-10008-C1 |
| CEP-2272A | CPE-757 | CDMG13008L-02 |
| CEP-2224 | CPE-750PA | CDMG16008-03 |
| CEP-2260A | CPE-750A | CDMG15008-03A |
| CEP-2280 | CPE-350A | CDS-15158-SMT-TR |
| CEP-2250 | CDM-10008 | CDS-40288 |
| CEP-4411AC | CDM-12008 | CDS-40288-L100 |
| CEP-1130 | CDM-13008 | CPE-2883 |
| CEP-1173 | CDM-16008 | CPE-4485 |
| CMT-1604-SMT-TR | CDM-20008 | |

Reason(s) for Change: *Factory location change*

F-723-001

Revision: A



Description of Change: *The factory in which these parts are manufactured is moving to a new location*

Affected Date Code: *July 1st, 2016*

Product Availability: *Currently available*

Additional Information: *No change to form, fit, or function*

PCN Approval:

Operations/Quality

A handwritten signature in black ink, appearing to read "Nigel H. Byrum".

Product Marketing

A handwritten signature in black ink, appearing to read "RMS".